Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00416

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513				
Exit Meeting Contact: Kevin Glaspy	Total Man Days: 3				
Pipeline Safety Representative(s): Donald Hankins					
Company Representative to Receive Report: Michael Fuller	Emailed Date:				
Company Representative's Email Address: mfuller2@ameren.com	01/13/2016				

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Design Testing and Construction	Champaign	Donald Hankins	Champaign	3	10/13/2015, 10/14/2015, 10/15/2015	Kevin Glaspy

Statement of Activities

On October 13, 14, & 15, 2015, a construction audit was conducted at Ameren Illinois, in Champaign, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

On October 13, 2015, an Ameren Illinois crew was installing a new plastic service line into 2005 John Drive, in Mahomet Illinois. The new service line was 1 inch Driscoplex pipe. The service line was air tested to 101 pounds for 14 minutes, with no leaks being found.

On October 14, 2015, an Ameren crew was installing a new service line into 1215 English Oak Drive, in Champaign, Illinois. The service line was a 1/2 inch Driscoplex pipe, ASTM E-2513, PE 2406/2708, connected to a 4 inch PE gas main. An air test was conducted at 102 pounds for 10 minutes, with no leaks being found during this audit.

On October 15, 2015, an Ameren crew was installing a new gas service line into 981 Iron Horse Place, in Monticello, Illinois. The service line was a 1 inch Driscoplex plastic service line, and was air tested to 101 pounds for 14 minutes, with no leaks being found during this audit.

Exit Statement

INSPECTION FINDINGS

Design Testing and Construction

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00416

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]